·	. /		NTIAL HAZARDOUS		IDENTIFICATION	NUMBER
	✓ •		T PRELIMINARY A FINAL STRATEGY		120 980	197 812
SI TE NAME	m/ >		ADDRESS	1. 1. 12		i Por
TY	STATE -	10 N	ZIP CODE	1000 14, 50- T COUNTY	TCH 33, 11110 TCOUNTY CODE	TONG DIST
ONG CREEK	1WD - 1	_	62526	MACON	1/5	12/
DAVE REC'D	NTH / DAY / YEA	DATE COM	PLETED <u>O/</u> Month/	DAY / YEAR	PRE HRS SCORE	
PLEASE CIRCL	E CORRECT CODE					
402	RCRA TSD - Per	rmitted or cl	osure candidate	es not to be li	sted. Excluded by	policy.
412			underground sto 1. NOTE: wasto		asoline and petrol Leligible.	eum
401	Oil/gas - Natu gas usable for	ral gas, nat fuel. Petr	ural gas liquio oleum, crude o	ds liquefied na il or any fract	itural gas, synthet ion thereof.	ic
407	Federal Facility - Federal agency financed from appropriations to the agency not Superfund. Investigated under Installation Restoration Program. (Department of Defense or similar program.) Excluded by policy.					
4 08 ~	Mining - Until HRS revision is completed by April 1988, sites cannot be scored. Data is usually high volume, low toxicity wastes. Wastes include those from mining; exploration, development or production of crude oil, natural gas or geothermal energy and dust from cement kilns.					
410					RA, or the handling ducer. Excluded by	
416	Radiation - Releases of source, by product or special nuclear material. Covered under Section 170 of Atomic Energy Act, Nuclear Regulatory Commission (NRC), Uranium Mill Tailings Radiation Control Act (UMTRCA). Excluded by statute.					
414/415	Special Wastes - Such as, brine, animal feed, and grain elevators are not covered under current HRS model. Excluded by policy.					
411	Fly-Ash - With respect to sites with substantial volumes of fly ash and others wastes from coal and fossil fuels burning. Can not use until HRS is revised in April 1988. Can not base evaluation made principally on the volume of those wastes but rather on the concentrations of the hazardous constituents of the waste.					
409	TSCA - Permitted or candidates not to be listed. Excluded by policy.					
4 03)413	Non Hazardous Substances - Substances not meeting the definition of being hazardous.					
404/405/406	SITE REQUIRED NO ADDITIONAL RESPONSE.					
FURTHER RESEARCH AND ANALYSIS REQUIRED, RECOMMEND SITE INSPECTION 5 ED 401-A0403 (No haz. Substance)						
PREPARER NAM	F		TITLE	· · · · · · · · · · · · · · · · · · ·	DATE,	mesiance)
Glinex	o 4.11	Laters	EPA	7	1/5/88	
	OF SUPERFUND CO		TITLE		DATE 1 1 111	
William D. Messenger						